- Q. Approximately how many involved cracked flywheel housings?
- A. I believe some of the documents indicated that approximately 100, 110 flywheel housings were replaced. Some of the documents indicated that.
- Q. So is that your best estimate of the number of cracked flywheel housings that were identified in those documents?
- A. No. As I said, the reports from Mr. Bowes is confusing on that point and kind of casts out -- I shouldn't say that. It puzzles me as to exactly how many flywheel housing failures there were.
- Q. I'll return to my question, sir. Based on your review of documents in this case, what is your understanding of the total number of cracked flywheel housings that occurred on C-10 or C-12 engines?
- A. To answer that question, I would have to look at the documents again. I don't have a number off the top of my head.
- Q. Not even an estimate?
- A. Not off the top of my head.

		•
1	Q.	Are those documents with you today?
2	Α.	I didn't bring any documents myself. I
3		thought all the documents would be here.
4	Q.	Consequently, you can't look at them?
5		MS. REIMER: For the
6		record, these are documents that were
7		produced in discovery by Caterpillar that
8		we presumed you had in your office and it
9		wasn't necessary to bring a freight truck
10		to bring all documents with us. These were
.11		documents that were produced by
12		Caterpillar.
13		MR. GRUNERT: And they were
14		subpoenaed, and there was no objection to
15		their production.
16		MS. REIMER: We certainly
17		didn't interpret the subpoena to require us
18		to bring documents that you already have in
19		your possession that you produced.
20		MR. GRUNERT: We will move
21		along and raise it with the Judge.
22		MR. SAMITO: Do you have
23		documents 1 though 4014. If you have them
24		here, he can start doing that.

MR. GRUNERT: I'm 1 interested in what --THE WITNESS: Can I see the subpoena, please. I thought it said something that I can't find right now. That's fine. Do you have an estimate as to how many of Q. 7 the C-10 and C-12 flywheel housing failures that have occurred involved fracture of the flywheel housing-to-engine block bolts? 10 Flywheel engine housing-to-engine block 11 Α. bolts? 12 Do you have an estimate as to how many of Q. 13 the C-10 and C-12 flywheel housing failures 14 that have occurred have involved fractures 15 of the flywheel housing-to-engine block 16 bolts? 17 Again, the question is for Trans-Spec or --18 Α. All C-10 and C-12 engines. 19 0. I don't know. I don't recall that 20 information. 21 Do you know from any source approximately 22 Q. what percentage of C-10 and C-12 engines 23

have experienced one or more flywheel

24

housing failures? 1 Again, that's the number that is in Α. 2 Mr. Valbert's report that is confusing to 3 It appears to be inconsistent 4 internally. 5 Regardless of your comments about Q. 6 Mr. Valbert or Mr. Bowes' report, I'm 7 asking what you know, sir? 8 I know Mr. Bowes' report. Α. Other than what Mr. Bowes knows, you don't Q. 10 have any information with respect to the .11 percentage of C-12 flywheel housings that 12 have failed? 13 I have the information that Mr. Bowes Α. 14 relied on. I don't know what Mr. Bowes 15 relied on, but I have the information that 16 was produced that seems to parallel what 17 Mr. Bowes said. 18 What do you infer from that information as 19 Ο. to the percentage of C-12 engines that have 20 experienced flywheel housing failures? 21 I can't tell that you. As I said, it's 22 Α. inconsistent. 23 Have you attempted to determine whether

24

Q.